





































































































SIRIO

DOCUMENT & PRINTER SOLUTIONS

Per richiedere assistenza:

Tel. 0266013718 - assistenza@sirioonline.com

Per ordinare consumabili:

Tel. 0266013718 - fax 0266016090 - ordini@sirioonline.com

Sirio srl

Via Vittorio Veneto 10 - 20092 - Cinisello Balsamo - MI -

info@sirioonline.com - www.sirioonline.com

Matricola

E205R863006

Attrezzature di proprietà della ditta **Sirio srl**.
Il conduttore si obbliga a dichiarare nei confronti
di terzi, intenzionati a procedere a pignoramento
o ad altre misure esecutive della cosa locata, che
la proprietà della stessa è del locatore.














































































































































MITSUBISHI ELECTRIC

ROOM AIR CONDITIONER
MODEL **MXZ-3HA50VF**  **<H>**

FUNCTION	V/N	V	COOLING			HEATING			R/C CODE	R/C
			220	250	280	220	250	280		
VOLTAGE		V	220	250	280	220	250	280	REFRIGERANT R410A	1.4 kg
FREQUENCY	Hz		50	50	50	50	50	50	NET WEIGHT	52 kg
CAPACITY	kW		5.0			5.0			WARRANTY PERIOD	5 YEARS
INPUT/SET	kW		1.25			1.25			WARRANTY PERIOD	5 YEARS
CURRENT	A		5.5	5.5	5.5	5.5	5.5	5.5	WARRANTY PERIOD	5 YEARS
MAX. CURRENT	A		18.0			18.0			WARRANTY PERIOD	5 YEARS
ROOM TEMP. RANGE	°C		16~30			16~30			WARRANTY PERIOD	5 YEARS
ROOM COOLING	kW		5.0			5.0			WARRANTY PERIOD	5 YEARS

MITSUBISHI ELECTRIC CORPORATION
MITSUBISHI ELECTRIC CONSUMER PRODUCTS (THAILAND) CO., LTD.
100/100-1, TANGKUNGSUKHONG RD., THAILAND
HONGKONG, CHINA

DATE OF PRODUCTION: 2011.03
SERIAL NO.: 13P01261
MADE IN THAILAND

REFRIGERANT R32

ALL THE REFRIGERANT
IS PRECHARGED IN THE
UNIT. NO ADDITIONAL
REFILLING IS REQUIRED.
DO NOT RECHARGE
THE REFRIGERANT.
RECHARGE ONLY
IF THE REFRIGERANT
IS LEAKED.

REFRIGERANT R32

ALL THE REFRIGERANT
IS PRECHARGED IN THE
UNIT. NO ADDITIONAL
REFILLING IS REQUIRED.
DO NOT RECHARGE
THE REFRIGERANT.
RECHARGE ONLY
IF THE REFRIGERANT
IS LEAKED.













